



SEZNAM VYTÝČOVACÍCH BODŮ

ZÚ	-640453.6358	-1195128.4081
1	-640455.7514	-1195126.2811
2	-640460.6825	-1195121.3232
3	-640466.4128	-1195115.5619
4	-640472.4611	-1195109.4807
5	-640481.4523	-1195100.4609
6	-640495.2285	-1195086.6236
7	-640503.4136	-1195079.2274
8	-640512.7248	-1195069.6278
9	-640520.1835	-1195054.8906
10	-640520.8516	-1195052.4718
11	-640521.9868	-1195046.0726
12	-640521.9143	-1195035.1105
S	-640464.2972	-1195117.6889
Z01	-640493.6722	-1195088.1545
Z02	-640498.0165	-1195084.0405
Z03	-640506.2131	-1195076.7308

Zodpovědný pracovník	Vypracoval	
Ing. Milán Bortoljšić	Ing. Jan Vondráček	
Investor: Povodí Moravy, s.p., Dřevařská 11, 60200 Brno	Kopie: 27. 690 06 Břeclav IČO 60710063, DIČ CZ60710063 tel.: 519 333 689, email: oqc@woc.cz	
Kat:	Formát	
Leska, ř.km 0,015-0,145, Dobšice, úprava koryta	Datum	duben 2020
DOKUMENTACE PRO PROVÁDĚNÍ STAVBY	Číslo stopy	
Příloha:	Mapka	Číslo přílohy
VYTÝČOVACÍ SCHEMA	1:350	E