




PF 1 KM 2.4709




PF 2 KM 2.4806




PF 3 KM 2.4942




PF 4 KM 2.5101




PF 5 KM 2.5276




PF 6 KM 2.5450




PF 7 KM 2.5606




PF 8 KM 2.5767




PF 9 KM 2.5920




PF 10 KM 2.6063




PF 11 KM 2.6221




PF 12 KM 2.6390




PF 13 KM 2.6587




PF 14 KM 2.6690




PF 15 KM 2.6814




PF 16 KM 2.6922




PF 17 KM 2.7035




PF 18 KM 2.7163




PF 19 KM 2.7300




PF 20 KM 2.7431




PF 21 KM 2.7523




PF 22 KM 2.7783




PF 23 KM 2.7930




PF 24 KM 2.8098




PF 25 KM 2.8392



PF 26 KM 2.8582



PF 27 KM 2.8882



VYPRACOVAN KONTROLOVAN STAVEBNÍK MÍSTO STAVBY NAČEZ STAVBY	Ing. Ondřej Polách		
	Povodí Moravy, s.p.		
	k.ú. Těšín		
STAVEBNÍ OBJEKT ČÁST	Těšínská, Těšín, ř.km 2,470 – 2,885, odtěžení nánosů, oprava opevnění		
PŘÍČNÉ PROFILY			D.5